

UNITED STATES GOVERNMENT

Memorandum

TENNESSEE VALLEY AUTHORITY

CDB '79 1101 004

TO : H. S. Fox, Director of Power Production, 716 EB-C (2)

FROM : Roy H. Dunham, Manager of Engineering Design, W11A9 C-K

DATE : November 1, 1979

SUBJECT: KINGSTON STEAM PLANT - ANNUAL ASH DISPOSAL AREA INSPECTION

*H.R.
Kingston
Ash Disposal*

Attached is a report from Ronald D. Powell to Frank D. Stansberry dated October 31, 1979 (CDB 791101 003), on the joint inspection of the ash disposal areas at Kingston Steam Plant which includes recommendations for corrective work. I concur in these recommendations.

Original Signed By

F. P. Lacy
Roy H. Dunham

GLB:RDP:TLT

Attachment

cc: D. B. Bowen, 6204 MIB-K
G. L. Buchanan, W3C126 C-K
 R. G. Domer, W9D224 C-K
 MEDS, E4B37 C-K
 E. F. Thomas, 550 CST2-C (Attachment)

RECEIVED		11:25 ✓			
NOV 2 '79					
CIVIL ENG. & DES. BRANCH					
IN	OUT	IN	OUT		
Date	Time	Date	Time		
		GLB	✓ 11:25		
		DLG			
		TJA			
		HCE			
		EIS			
		REH			
		HSS			
		MAL			
✓ 11:20		FDS	✓ 11:31		
✓ 11:24		RJB	✓ 11:31		
		JPF			
		RAD			
		OHR			
		RSE			
		JHK			
		SDS			
		RWA			

✓ 5 11:30 RDP 5 11:35
 ✓ 5 11:30 RDP 5 11:35



UNITED STATES GOVERNMENT

Memorandum

TENNESSEE VALLEY AUTHORITY

CDB '79 11 01 003

TO : Frank D. Stansberry, Head Civil Engineer (Site Development, Highway, Railroad, and Bridge Design), W3A52 C-K

FROM : Ronald D. Powell, Civil Engineer (Site Development, Highway, and Railroad Design), W3B69 C-K

DATE : October 31, 1979

SUBJECT: KINGSTON STEAM PLANT - ANNUAL ASH DISPOSAL AREA INSPECTION

Kingston Ash Disposal

On September 13, 1979, Meigs Brewer of P PROD and I inspected the ash disposal areas at Kingston Steam Plant. We were accompanied on the inspection by Coy Wood, Yard Operations Supervisor. Findings were discussed with Ford Clayton, Assistant Plant Superintendent.

The last annual inspection was made on August 16, 1978 (CDB 781005 007).

On the attached print of drawing 10N420, the different areas are designated.

Change in Dikes Since Last Inspection

There has been no significant change in the dikes since last year's annual inspection.

A small area of surface wetness was observed at the toe of the exterior slope of the south end of dike C (picture 1). It could not be determined whether this condition was due to seepage or a concentration of surface runoff (recommendation 1).

Some areas of the dike slopes, both interior and exterior, have an excellent vegetative cover (pictures 2 and 3); while other areas have a very sparse vegetative cover or are completely bare (pictures 6, 7, and 9 and recommendation 2). Small erosion gullies have developed in parts of the bare areas.

Placement of a bottom ash berm along the interior dike slopes of the ash disposal area is in progress (picture 6).

A finger dike of bottom ash is under construction parallel to and 200± feet north of the east end of the divider dike. This finger dike should provide some relief from the effects of wave action and wind load on the buoyant skimmer in the divider dike flow-through spillway.

The tops of all dikes are smooth and sloped to the inside with a good crushed stone surface.

Change in Pond Operation Since Last Inspection

There has been no change in pond operation since last year's annual inspection.



Frank D. Stansberry
October 31, 1979

KINGSTON STEAM PLANT - ANNUAL ASH DISPOSAL AREA INSPECTION

Condition of Spillways, Skimmers, and Outlets

The standard spillways and skimmers in the stilling pool area appear to be in good condition and functioning properly. The spillway outlets are discharging equally, and the concrete end wall is in good condition. The riprap outfall to the intake channel appears to be in good condition with no sign of erosion. There was no sign of loss of ash into the intake channel. The weep holes in the concrete end wall of the spillway outlet pipes were seeping; however, the dike slope behind the end wall appeared to be dry and well compacted.

The two buoyant skimmers in the divider dike flow-through spillway appear to be functioning properly with minimal loss of ash into the stilling pool area (picture 4). However, a fly ash slurry was observed covering at least 50 percent or more of the stilling pool area surface (picture 8).

The plant-constructed spillways of the initial ash disposal area in the east end of the north dike were submerged; however, they appeared to be functioning adequately.

The outlets of the plugged and abandoned spillways in the northern portion of dike C were submerged by Watts Bar Lake and could not be inspected for leakage.

Action on Recommendations of Last Inspection

1. All badly eroded areas of the dike slopes have been repaired; however, small erosion gullies are beginning to develop in parts of the bare areas.
2. Placement of a heavy ash berm along the interior dike slopes of the ash disposal area is in progress (picture 6). This berm should prevent further erosion of the dike slopes due to wave action.
3. Some areas of the dike slopes have an excellent vegetative cover (pictures 2 and 3), while other areas are completely bare (pictures 6, 7, and 9).
4. The spillway access area has been regraded and appears to be draining adequately.
5. Crushed stone surfacing has been placed on top of the ash disposal area dikes and the spillway access.
6. Some areas of the divider dike slopes are badly eroded and do not appear to have had any maintenance work.
7. The channel bottom has been lowered and two longer buoyant skimmers have been placed in the flow-through spillway (picture 4). These skimmers appear to be functioning properly.


Frank D. Stansberry
October 31, 1979

KINGSTON STEAM PLANT - ANNUAL ASH DISPOSAL AREA INSPECTION

8. Riprap placement on the divider dike flow-through spillway slopes has deteriorated badly and does not appear to have had any maintenance work (picture 5).
9. A private contractor is presently removing some of the fly ash slurry covering the stilling pool area surface.
10. The weep holes in the concrete end wall of the spillway outlet pipes were seeping; however, not excessively. The dike slope behind the end wall appears dry and well compacted.

Recommendations

1. Plant personnel should regrade the area of surface wetness at the south end of dike C (picture 1) so that surface runoff is not concentrated at the toe of the dike slope and will flow into Watts Bar Reservoir. This area should then be observed for a period of time to determine if a seepage problem exists.
2. Fertilize and reseed all areas of the dike slopes where an adequate vegetative cover has not been established with type 6, mixture E, in accordance with sections 180 and 182 of the T-1 Specifications.
3. Repair any earthfill dike slope erosion that may occur prior to the establishment of an adequate vegetative cover.
4. Repair badly eroded areas of the divider dike slopes.




Ronald D. Powell


RDP:TLT

Attachments

Concur:



Frank D. Stansberry



G. L. Buchanan

10/31/79 - FDS:TLT

cc: G. L. Buchanan, W3C126 C-K (Attachments)

10/31/79 - GLB:TLT

cc: D. B. Bowen, 6204 MIB-K
(Attachments)

R. G. Domer, W9D224 C-K
(Attachments)

Roy H. Dunham, W11A9 C-K
MEDS, E4B37 C-K (Attachments)

KINGSTON

1972




(1)

Wet area at toe of slope of East
dike adjacent to stilling pool.



(2)

Exterior slope of East Dike.
Note excellent vegetative cover.



(3)

Interior slope of East dike inside
stilling pool area. Note excellent
vegetative cover.

KINGSTON STEAM PLANT
1979



(4)

Looking into stilling pool area from divider dike. Note fly ash slurry on water surface in front of floating skimmer.



(5)

Looking into divider dike float-through spillway. Note coarse riprap cover on divider dike slope.



(6)

Looking southward along interior slope of dike from location of baffle box. Note baffle box berm adjacent to dike slope and lack of vegetative cover on slope.

KINGSTON STEAM PLANT
1979



(7)

Looking Northwest along interior slope of East dike from location of abandoned spillways. Note lack of vegetative cover on dike slope in this area.





(8)

Looking North across stilling pool from South dike. Note fly ash slurry on water surface around standard spillways.



(9)

Looking into standard spillway outlets. Note absence of vegetative cover on dike slope above spillway outlets.



NOTES:
1. OWN CHARTERED AND ASSOCIATED EDITIONS IS DECODED IN ALPHABETICAL ORDER.

10

Photograph taken
point in this di-

2		15-6-7 RESTORING 6 KIDS		RIB TO TUBE		NIN	
ITEM	ITEM	ITEM	ITEM	ITEM	ITEM	ITEM	ITEM
Reinon Chem Bond	4	Surgeon Cut	1	Surgeon Cut	1	Surgeon Cut	1
1	15-6-7	1	15-6-7	1	15-6-7	1	15-6-7
Adhesive	1	1	1	1	1	1	1
ITEM NO.	ITEM NO.	ITEM NO.	ITEM NO.	ITEM NO.	ITEM NO.	ITEM NO.	ITEM NO.
ITEM NO.	ITEM NO.	ITEM NO.	ITEM NO.	ITEM NO.	ITEM NO.	ITEM NO.	ITEM NO.
15-6-7	15-6-7	15-6-7	15-6-7	15-6-7	15-6-7	15-6-7	15-6-7
DR. CALLIGRADI	DR. CALLIGRADI	DR. CALLIGRADI	DR. CALLIGRADI	DR. CALLIGRADI	DR. CALLIGRADI	DR. CALLIGRADI	DR. CALLIGRADI
CHAD ZACH GARDEN	CHAD ZACH GARDEN	CHAD ZACH GARDEN	CHAD ZACH GARDEN	CHAD ZACH GARDEN	CHAD ZACH GARDEN	CHAD ZACH GARDEN	CHAD ZACH GARDEN
DR. D. S. TONE	DR. D. S. TONE	DR. D. S. TONE	DR. D. S. TONE	DR. D. S. TONE	DR. D. S. TONE	DR. D. S. TONE	DR. D. S. TONE
J.P. FOX	J.P. FOX	J.P. FOX	J.P. FOX	J.P. FOX	J.P. FOX	J.P. FOX	J.P. FOX
ENGINEER = R							

PLAN - RAISING ASH DISPOSAL

KINGSTON STEAM PLANT

PROJECT 7202